

IP-DIN / IP-OA

Software version: 2.1.11

Release date: 18/11/2021

Hardware compatibility: Version B

Article numbers: NWAAES0160 / NWAAES0100

ENHANCEMENTS & NEW FEATURES

Reference	Description
0003654	Changed "IO Netrix 0/1" to "IO Netrix 0/1 (Only 1)" in the
	settings webpage.
0003691	Added 'Fast ping' option in the website.

BUGFIXES

Reference	Description
0003715	Door activation was incorrectly sent to the iLink as type medallion.
0003705	RFID button did not blink in toilet-assist state.
0003653	If this sequence is send out (UDP medallion -> UDP away -> UDP call), the call will be send to the Netrix as medallion.

